

Waterway Inspection Report

General Information:

Date	9-3-26
Location	Century Village Boca

Technician(s):

Joey

Weather Conditions:

Temperature	90	Wind Speed	5-12	Wind Direction	N/A
-------------	----	------------	------	----------------	-----

SITE/ LAKE #	INSPEC- TION	TREAT- MENT	SKIFF	SIDE-BY- SIDE	BACK- PACK	ALGAE	GRASSES	SUB- MERGED	FLOATING	WATER LEVEL
All	✓	✓		✓			✓			High

Wildlife Observations:

Birds, Fish, Ducks

Comments:

Today we treated for shoreline grasses. No signs of surface algae at this time. Water levels are high. We also picked up debris out of big lake. All lakes are looking healthy.













